Report No:	LR DON 1312	Ozone
Issue Date:	August 2004	Monitoring in Laundries
Copy No:		
		Prepared By:
		Scientifics Ltd 4 Hexthorpe Road Doncaster South Yorkshire
Author:W Halkett	GRSC Cert of Occ Hyg	DN4 0AE

Copyright 2004 Scientifics Ltd
This document was supplied to JLA Ltd under the terms of a contract. The information contained in is confidential and shall not be divulged without the permission of Scientifics Ltd. It shall not be reproduced, except in whole without the written approval of Scientifics Ltd. The document or the information in it shall not be used for any purpose outside of the terms of the contract without the express permission of Scientifics Ltd.

Issued by: Scientifics Ltd, 4 Hexthorpe Road, Doncaster, DN4 0AE.

Tel: 01302 380150 Fax: 01302 380158

Prepared For:

JLA Ltd Meadowcroft Lane Halifax Road Ripponden HX6 4AJ

CONTENTS

		Page
CONT	TENTS	1
1.	INTRODUCTION	2
2.	MONITORING	2
3.	RESULTS	2
4.	DISCUSSION	2
5.	CONCLUSIONS	2
6.	RECOMMENDATIONS	2
7.	DISTRIBUTION LIST	3
APPE	NDIX A – RESULTS	

1. INTRODUCTION

As requested a visit was made to the laundry rooms of a residential home in Bury and a hotel in Blackpool to undertake atmospheric monitoring for ozone.

2. MONITORING

Monitoring for ozone was carried out using dosemeter tubes which react with ozone by converting nitrite to nitrate. The tube is subsequently analysed for nitrate.

3. RESULTS

The results are appended to the report.

4. DISCUSSION

Ozone is produced in situ in the laundries and fed directly to the washing machines.

Ozone is being used as a disinfectant and a bleaching agent.

The atmospheric limits for ozone are given in HSE publication EH 40 "Occupational Exposure Limits". For ozone the limit given is for short term exposure of 15 minutes. This is due to the fact that ozone is highly reactive and acute (short term) symptoms, especially irritation of the respiratory tract and eyes, will occur rapidly if high concentrations are encountered. This exposure limit will apply through the working day.

5. CONCLUSIONS

From the results it can be seen that the concentrations of ozone are within the limits as given in EH 40. The exposure at the front of the washing machines is higher due to residual ozone in the machines being released when doors are opened following washing.

6. RECOMMENDATIONS

To ensure that the systems remain sealed from the production area to the washing machine pipework should be check on a regular basis to ensure it is intact.

7. DISTRIBUTION LIST

Report No: LR DON 1312

Title: Ozone Monitoring in Laundries

Copy No: Recipient:

01-04. J Hook, JLA Ltd, Meadowcroft Lane, Halifax Road, Ripponden

West Yorkshire, HX6 4AJ.

05. W Halkett, Scientific Officer, Scientifics Ltd, 4 Hexthorpe Road,

Doncaster, DN4 0AE.

Additional Copies

06-30 (10.08.04). J Hook, JLA Ltd, Meadowcroft Lane, Halifax Road, Ripponden West Yorkshire, HX6 4AJ.

31-40 (17.08.04) J Hook, JLA Ltd, Meadowcroft Lane, Halifax Road, Ripponden

West Yorkshire, HX6 4AJ.

41-65 (07.01.05) J Hook, JLA Ltd, Meadowcroft Lane, Halifax Road, Ripponden

West Yorkshire, HX6 4AJ.

66-115 (18.01.05) J Hook, JLA Ltd, Meadowcroft Lane, Halifax Road, Ripponden

West Yorkshire, HX6 4AJ.

CONFIDENTIALITY

The information contained in this report shall not be disclosed outside Scientifics Ltd without the permission of the client.

In addition to those named on the distribution list above, the information contained in this report will be restricted to:

Category of Restriction				
Scientifics Ltd (unrestricted)				
	Distribution List Only			
✓	SHE Group Only			

APPENDIX A
RESULTS

APPENDIX A - RESULTS

Table 1

Sample No	Sample Description		Ozone Detected On Tube (µg)	Airborne Concentration (µgm ⁻³)	Airborne Concentration (ppm)
DOH05074/01	Nursing Home –Personal		0.04	101	0.05
DOH05074/02	Nursing Home – Personal		0.04	101	0.05
DOH05074/03	Hotel – Personal		0.08	196	0.098
DOH05074/04	Hotel – Adjacent Machines		0.07	167	0.084
Occupational Exposure Standard		8 Hour	Time Weighted Average	400	0.2
(C	DES)	15 Minute Time Weighted Average		400	0.2